


# SCHALBURG HEATING AND COOLING

7350 E. State Road 42  
Terre Haute, IN 47803

1706 Bolton Road  
1706 Bolton Rd  
West Terre Haute, IN 47885

INVOICE	#33563
SERVICE DATE	Apr 05, 2024
INVOICE DATE	Apr 09, 2024
DUE	Upon receipt
AMOUNT DUE	<b>\$225.00</b>

## CONTACT US

 (812) 877-4822

 tanyabrock@schalburgheatingandcooling.com

## INVOICE

Services	qty	unit price	amount
HVAC Inspection	1.0	\$225.00	\$225.00
HVAC inspection for real estate agent			

The gas was shut off to the furnace due to a rotted 4" to 6" increaser and a plugged brick flue. Unplugged brick flue and made temporary repairs to metal flue to allow testing. When 1st turning furnace on in heat mode the burners did not light completely due to debris in the lighting track. After that period it lit with no problem. The coil and filter were decent and there was no measurable CO coming from the furnace. All registers flowed. The thermostat works for both heat cool and fan operation. The air conditioner is not flat and starts and runs when called upon to do so.

Subtotal	\$225.00
Total Tax	\$0.00
IN Sales Tax (7%)	\$0.00
<b>Total</b>	<b>\$225.00</b>

SCHALBURG HEATING AND COOLING

<http://schalburgheatingandcooling.com>