



# E.H. McCalister Sewer & Drain LLC

April 9, 2024

Dzierna Rental Services  
4700 W Innovations Dr  
Bloomington, IN

Ref: Septic Inspection @ 1706 Bolton Rd, West Terre Haute, IN 47885

Attn: Judy Vitaliano

We inspected the septic system at 1706 Bolton Rd on April 8, 2024. We found one 1000-gal septic tank, approximately 1200 square feet of Sand filter system. This system does meet State and County Board of Health code.

The septic tank was uncovered and checked. The tank was in good condition. The effluent baffle was in place and in good condition and was a filtered baffle. The septic tank does require pumping at this time. It is recommended that the tank be pumped every 2 to 3 years thereafter.

We located one sand filtered system measuring 15'X 80 for a total of 1200 square feet of system. The property was probed, and no other drains or finger system were found. The system was not stress tested due to no water available, however, there were no signs at the effluent baffle of any problems. The filter in the baffle should be cleaned every 6 months at a minimum.

This is a 3-bedroom home. The property water source is in excess of 50' from the septic system.

This system is a functional and legal system at this time and does meet code. This inspection does not imply any warranties or guarantees, due to the many various situations that may occur with septic systems, from this day forward.

Sincerely,

Trina J Earley  
Owner

Enclosure: Invoice, pictures

